

# HYDRO PRESSURE TEST

|                                   |                                                         |                  |
|-----------------------------------|---------------------------------------------------------|------------------|
| TC No.: HPT/MM6/SP/RQ/029/25      | Model No.: MMSRQ-6                                      | Date: 09-09-2025 |
| Type and Capacity of Extinguisher | : MMSRQ-6-Kanex M Foam SP Fire Extinguisher Cap. 6 Ltr. |                  |
| Batch Number                      | : MMSRQ6 029/25                                         |                  |
| Batch Quantity                    | : 21.00 Nos.                                            |                  |
| Serial Numbers                    | : 00561 To 580 And 565A                                 |                  |
| Month of Manufacturing            | : Sep/25                                                |                  |

| Sr. Nos.                                                    | Result | Sr. Nos. | Result | Sr. Nos. | Result | Sr. Nos. | Result |
|-------------------------------------------------------------|--------|----------|--------|----------|--------|----------|--------|
| Burst test conducted on 565A and removed from the Lot/Batch |        |          |        |          |        |          |        |
| 561                                                         | Pass   | 562      | Pass   | 563      | Pass   | 564      | Pass   |
| 565                                                         | Pass   | 566      | Pass   | 567      | Pass   | 568      | Pass   |
| 569                                                         | Pass   | 570      | Pass   | 571      | Pass   | 572      | Pass   |
| 573                                                         | Pass   | 574      | Pass   | 575      | Pass   | 576      | Pass   |
| 577                                                         | Pass   | 578      | Pass   | 579      | Pass   | 580      | Pass   |

**Remarks:** This is to certify that the above mentioned Fire Extinguishers are tested for hydraulic pressure of 35 bar for 2.5 minute and found satisfactory. No any leakage observed.



**Authorized Signatory**