



Follow-up Service Inspection Report
S364191250213091911

INSPECTION DETAILS			
Date:	2025-02-13	File Number.:	S36419
Responsible Office:	Northbrook	Volume:	1
Inspection Center:	289	CCN:	UQGS2
Product Type:	Life Safety & Security	UL Rep Name:	Sergiu Stanilescu
Deliverable Type:	Recognized	UL Rep ID:	12797
Party Site Number:	671895	Subscriber Factory No.:	100608-968
Applicant:	Fire Automatique Innovations S.a.r.l. (2403251)		
Nature of visit:	Regular Inspection	Sample Status:	eTag Sample Selected
UL Marks Used?	No	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental Conditions Required?	No

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
C0410	HEAT-AUTOMATIC FIRE DETECTORS - COMPONENT (UQGS2)	1	No

UL-OWNED EQUIPMENT CALIBRATION	
No UL owned inspection, measuring and test equipment used during inspection.	

COMMENTS	
Additional Comments	Etag Reference Number: F250443643 for annual tests was issued. Tube activation temperature recorded - at 156.97 C degrees. Calibration of test chamber done 11.12.2024, next calibration 12.2025.
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.