

# HYDRO PRESSURE TEST

|                                   |                                                                              |                  |
|-----------------------------------|------------------------------------------------------------------------------|------------------|
| TC No.: HPT/MOD10/CA/RQ/086/26    | Model No.: KMCRQ-10                                                          | Date: 02-07-2026 |
| Type and Capacity of Extinguisher | : KMCRQ-10-Kanex Clean Agent Modular HFC Based Fire Extinguisher Cap. 10 Kg. |                  |
| Batch Number                      | : KMCRQ10 086/26                                                             |                  |
| Batch Quantity                    | : 10.00 Nos.                                                                 |                  |
| Serial Numbers                    | : 00851 To 860                                                               |                  |
| Month of Manufacturing            | : Jul/26                                                                     |                  |

| Sr. Nos.                                                            | Result | Sr. Nos. | Result | Sr. Nos. | Result | Sr. Nos. | Result |
|---------------------------------------------------------------------|--------|----------|--------|----------|--------|----------|--------|
| Burst test conducted on 00851 To 860 and removed from the Lot/Batch |        |          |        |          |        |          |        |
| 851                                                                 | Pass   | 852      | Pass   | 853      | Pass   | 854      | Pass   |
| 855                                                                 | Pass   | 856      | Pass   | 857      | Pass   | 858      | Pass   |
| 859                                                                 | Pass   | 860      | Pass   |          |        |          |        |

**Remarks:** This is to certify that the above mentioned Fire Extinguishers are tested for hydraulic pressure of 35 bar for 2.5 minute and found satisfactory. No any leakage observed.



**Authorized Signatory**