

# HYDRO PRESSURE TEST

|                                   |                                                                          |                  |
|-----------------------------------|--------------------------------------------------------------------------|------------------|
| TC No.: HPT/MOD5/CA/FK/RQ/031/26  | Model No.: KMCRQ-5-FK                                                    | Date: 03-04-2026 |
| Type and Capacity of Extinguisher | : KMCRQ-5-FK-Kanex Clean Agent FK5112 Based Fire Extinguisher Cap. 5 Kg. |                  |
| Batch Number                      | : KMCRQ5FK 031/26                                                        |                  |
| Batch Quantity                    | : 10.00 Nos.                                                             |                  |
| Serial Numbers                    | : 00301 To 310                                                           |                  |
| Month of Manufacturing            | : Apr/26                                                                 |                  |

| Sr. Nos.                                                            | Result | Sr. Nos. | Result | Sr. Nos. | Result | Sr. Nos. | Result |
|---------------------------------------------------------------------|--------|----------|--------|----------|--------|----------|--------|
| Burst test conducted on 00301 To 310 and removed from the Lot/Batch |        |          |        |          |        |          |        |
| 301                                                                 | Pass   | 302      | Pass   | 303      | Pass   | 304      | Pass   |
| 305                                                                 | Pass   | 306      | Pass   | 307      | Pass   | 308      | Pass   |
| 309                                                                 | Pass   | 310      | Pass   |          |        |          |        |

**Remarks:** This is to certify that the above mentioned Fire Extinguishers are tested for hydraulic pressure of 35 bar for 2.5 minute and found satisfactory. No any leakage observed.



**Authorized Signatory**