

# HYDRO PRESSURE TEST

|                                   |                                                                          |                  |
|-----------------------------------|--------------------------------------------------------------------------|------------------|
| TC No.: HPT/MOD5/CA/FK/RQ/029/26  | Model No.: KMCRQ-5-FK                                                    | Date: 03-04-2026 |
| Type and Capacity of Extinguisher | : KMCRQ-5-FK-Kanex Clean Agent FK5112 Based Fire Extinguisher Cap. 5 Kg. |                  |
| Batch Number                      | : KMCRQ5FK 029/26                                                        |                  |
| Batch Quantity                    | : 10.00 Nos.                                                             |                  |
| Serial Numbers                    | : 00281 To 290                                                           |                  |
| Month of Manufacturing            | : Apr/26                                                                 |                  |

| Sr. Nos.                                                            | Result | Sr. Nos. | Result | Sr. Nos. | Result | Sr. Nos. | Result |
|---------------------------------------------------------------------|--------|----------|--------|----------|--------|----------|--------|
| Burst test conducted on 00281 To 290 and removed from the Lot/Batch |        |          |        |          |        |          |        |
| 281                                                                 | Pass   | 282      | Pass   | 283      | Pass   | 284      | Pass   |
| 285                                                                 | Pass   | 286      | Pass   | 287      | Pass   | 288      | Pass   |
| 289                                                                 | Pass   | 290      | Pass   |          |        |          |        |

Remarks: This is to certify that the above mentioned Fire Extinguishers are tested for hydraulic pressure of 35 bar for 2.5 minute and found satisfactory. No any leakage observed.



Authorized Signatory